Hazardous Waste Compliant Compliant Log

FORM

| Handler Safety Kleen, Inc. | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| | F(X) GEN(X) KG() SQ() TRA() B() UOM() UOB() NOT A GEN() | |
| Handler Name: Safety Kleen (Wichita), Inc. | AT CL RCRIS 9/30/07 | |
| Street: 2549 N. New York City: Wichi | ta, KS 67219 County: Sedgwick | |
| dios. 20 lo N. Now Low | M M D D Y Y | |
| EVALUATION New X Followup: Date (on site) | Date (of letter) 0 7 2 2 0 2 Delete | |
| Date 0 2 0 6 1 3 Agency S Type CSE | Reason 0 1 Person D L T District S C | |
| Areas of Evaluation (EV - Evaluated, NE - Not Evaluated, NA - Not Applicable) | | |
| Generator Transporter DCH | V DLB - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - | |
| GOR TWD DGS E | V DLT [,, | |
| | RCRA RECORDS | |
| | SUM L | |
| COMMENTS CLUAN HARDES KANSO | is -UC - NOW name | |
| | | |
| | | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 | |
| · · · · · · · · · · · · · · · · · · · | | |
| VIOLATION # _1 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type | VIOLATION # _2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance | VIOLATION # _2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y Y Area. Schl'd 0 7 1 5 0 2 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(B) Description: One 40-gallon satellite Returned to Compliance drum not marked with the words M M D D Y Y A hazardous waste in Schi'd 0 7 1 5 0 2 | |
| VIOLATION # _1 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(B) Description: One 40-gallon satellite Returned to Compliance drum not marked with the words M M D D Y Y | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y Y Area. Schl'd 0 7 1 5 0 2 Actual 0 6 1 2 0 2 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S R Regulation Citation: K.A.R. 28-31-4(j)(1)(B) Description: One 40-gallon satellite Returned to Compliance drum not marked with the words M M D D Y Y Y hazardous waste in Schl'd 0 7 1 5 0 2 building B. Actual 0 6 1 2 0 2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y Y Area. Schl'd 0 7 1 5 0 2 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S G P T 1 S R Regulation Citation: K.A.R. 28-31-4(j)(1)(B) Description: One 40-gallon satellite Returned to Compliance drum not marked with the words M M D D Y Y A hazardous waste in Schi'd 0 7 1 5 0 2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y Actual 0 6 1 2 0 2 VIOLATION # 3 Date Determined 0 6 1 2 0 2 New Change X Delete Comments | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S GPT 1 SR Regulation Citation: K.A.R. 28-31-4(j)(1)(B) Description: One 40-gallon satellite Returned to Compliance drum not marked with the words M M D D Y Y Y hazardous waste in Schl'd 0 7 1 5 0 2 building B. Actual 0 6 1 2 0 2 VIOLATION # 4 Date Determined 0 6 1 2 0 2 | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S R Regulation Citation: K.A.R. 28-31-4(j)(1)(A) Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y Y Actual 0 6 1 2 0 2 VIOLATION # 3 Date Determined 0 6 1 2 0 2 | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Class Priority Type S | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Comments Agency Number S Required to Compliance S Required to Compliance New Change S Returned to Compliance Regulation: Two open satellite drums Returned to Compliance Two open satellite drums Returned to Compliance in the lab and the processing Actual 0 6 1 2 0 2 New D D Y Y Y D D D D D D D D D D D D D D | VIOLATION # 2 Date Determined 0 6 1 2 1 2 0 2 New | |
| VIOLATION # 1 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number Area Priority Type S R SR Regulation Citation: K.A.R. 28-31-4(j)(1)(A) SR Description: Two open satellite drums Returned to Compliance in the lab and the processing M M D D Y Y area. Schl'd 0 7 1 5 0 2 Actual 0 6 1 2 0 2 VIOLATION # 3 Date Determined M M M D D Y Y Actual O 6 1 2 0 2 New Change X Delete Comments Schl'd O 6 1 2 0 2 Regulation Citation: Schl'd Schl'd Schl'd O 6 1 2 0 2 New Change X Area Class Priority Type Regulation Citation: KAR 28-31-6/ 40CFR264.171 / Permit Cond. III. C. | VIOLATION # 2 Date Determined 0 6 1 2 0 2 New Change X Delete Comments Agency Number | |

FORM B

Rev. 4-94



| ID Number K S D 0 0 7 2 4 6 8 4 6 Handler Name: Safety Kleen (Wichita), Inc. | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| VIOLATION # 5 Date Determined M M D D D Y Y Y O D D O D O D O D O D O D O | VIOLATION # 6 Date Determined 0 6 1 2 0 2 New Change X Delete Comments | |
| Agency Number Area Class Priority Type S GPT 1 SR Regulation Citation: K.A.R. 28-31-4(j)(2) | Agency Number Area Class Priority Type S DGS 1 PC Regulation Citationy Permit Condition II. A. | |
| Description: Improper start accumulation date on 2 55-gallon satellite drums in schrd the processing area. Returned to Compliance N N N D D Y Y 1 5 0 2 1 2 0 2 | Description: Failure to maintain the roofs in buildings B, J, I, & D. 40 CFR 264 31 Schlid 0 7 1 5 0 2 Actual | |
| VIOLATION # 7 Date Determined 0 6 1 3 0 2 New Change X Delete Comments | VIOLATION # 8 Date Determined 0 6 1 3 0 3 New Change X Delete Comments | |
| Agency Number Area Class Priority Type S DGS 2 PP C | Agency Number Area Class Priority Type S DGS 2 PC | |
| Regulation Citation K.A.R. 28-31-4(k)/Permit Gond. III.G. Description: 138 violations on the Returned to Compliance daily & weekly inspection logs. M M D D Y Y 40 CFR 264, /5(L) Schl'd 0 7 1 5 0 2 Permit Gold. II.E. Actual 0 7 1 1 0 2 | Regulation Citation: AR 28 84 MK)/Permit Conditin I.I.2.e. Description: Failure to provide 61 Returned to Compliance daily inspection logs for M M D D Y Y Y May and June 2001. Schl'd 0 7 1 5 0 2 YOCFR 264.13(a)(5) Actual 0 7 1 1 0 2 | |
| VIOLATION # 9 Date Determined M M D D D T Y Y T T T T T T T T T T T T T T | VIOLATION # Date Determined Delete Comments | |
| Agency Number Area Class Priority Type S C 2 S R Regulation Citation: KAR28-31-4(q)/40CFR262/Pomit Conduction. | Agency Number Area Class Priority Type S Regulation Citation: | |
| Description: Failure to file a notice Returned to Compliance with the Secretary of KDHE for M M D D Y Y Y exporting hazardous waste Schi'd 0 7 1 5 0 2 to a foreign source 5 times. Actual 0 7 1 1 5 0 2 | Description: Returned to Compliance M M D D Y Y | |
| ENFORCEMENT New X Change Delete Date 0 2 0 6 1 3 Number Agency S Type 1 2 0 District S C Person D L T | | |
| Agency Violation Number Area Agency Violation Number Area S S S S S S S S S S S S S S S S S S S | | |
| Comments: | | |





KANSAS DEPARTMENT OF HEALTH & ENVIRONMENT

BILL GRAVES, GOVERNOR Clyde Graeber, Secretary

July 22, 2002

Mr. Russell J. Dunn Safety-Kleen, Inc. 2549 N. New York Ave. Wichita, KS 67219

RE:

Hazardous Waste Compliance Inspection of June 12 & 13, 2002.

Safety-Kleen, Inc.

EPA ID No.: KSD007246846

Sedgwick County

Dear Mr. Dunn:

Our office received your letter dated July 11, 2002, that provides documentation that you have taken actions to correct deficiencies found during the June 12 and 13, 2002, hazardous waste compliance inspection. Based on this information, you have satisfactorily corrected violations 1, 2, 3, 4, 5, 7, 8, and 9.

Please provide additional information concerning violation # 6: Permit Condition II. A., failure to maintain the roofs in Buildings B, J, I, and D. We are requesting an expected date of completion on the repairs to the roofs on buildings B, J, and I. Your response must be submitted to me by August 5, 2002. Additionally, please submit final documentation when the roof repairs have been completed.

Please be aware that a report of this inspection is submitted to the Bureau of Waste Management (BWM) in Topeka for review. Each report is reviewed and an evaluation is made to determine if additional enforcement is warranted. A penalty may be issued by BWM for violations identified during this inspection.

Your cooperation with the hazardous waste management program is appreciated. If you have questions concerning this letter, please call me at (316) 337-6039.

Sincerely,

Debbie Travis

Environmental Technician

Delilie Trais

Bureau of Environmental Field Services

cc: John Mitchell, Bureau of Waste Management, Topeka Mark Duncan, Compliance and Enforcement, Topeka SCDO, File July 11, 2002

CERTIFIED MAIL No. 7000-1530-0004-8342-3602 RETURN RECEIPT REQUESTED

Ms. Debbie Travis Kansas Department of Health and Environment Bureau of District Operation Waste Management Programs 130 S. Market, Suite 6050 Wichita, Kansas 67202-3802

RE:

Notice of Non-Compliance Safety-Kleen (Wichita) Inc.

KSD007246846

Dear Ms. Travis,

In response to your Notice of Non-Compliance for the above referenced facility dated June 13, 2002, please consider the following corrective actions that we believe will alleviate the Department's concerns over these matters.

Citation:

KAR 28-31-4(j)(1)(A). Two (2) open satellite drums in the Lab and the

Processing Area.

Response:

During the inspection, two open drums were noted. On the first drum, which was located in the Laboratory, the small bung opening was open to allow the drum to breathe during filling operations. The second drum was the PPE drum located on the drum dock that had a small amount of PPE overhanging the lip of the drum. As noted on your Notice, both of these items were corrected during the inspection. In addition, we have conducted additional training with all of the affected employees on the operation of satellite accumulation areas.

Citation:

KAR 28-31-4(j)(1)(B). 40-gallon satellite drum not marked with the words

"Hazardous Waste", Building B.

Response:

During the inspection, the satellite accumulation drum located in Building B was missing the Hazardous Waste label. As noted on your Notice, this item was corrected during the inspection and the issue was covered in the employee

training identified above.

Citation:

KAR 28-31-4(g)(A) / Permit Condition III.C. 55-gallon storage drum is not in

good condition in Building C.

Ms. Debbie Travis July 10, 2002 Page 2 of 4

Response:

During the inspection, as drum was noted with a bulging lid. Safety-Kleen had received the drum on May 26, 2002 and noted that it was under pressure. Following our normal receiving procedures we vented the pressure from the drum prior to placing the drum in storage. However, we failed to overpack the drum, thus ensuring its integrity. As noted in your Notice, this item was corrected during the inspection. In addition, we conducted follow-up training with our warehouse workers and facility inspectors in this issue.

Citation:

KAR 28-31-4(g)(2) / Permit Condition III.B.1. No start accumulation date on 2 labpack storage containers in Building J.

The facility utilizes adhesive "piggyback" labels for each drum received. These

Response:

labels provide the unique tracking number and the accumulation start date. During the inspection, two containers were missing the portion of the "piggyback" label that contains the words "Start Accumulation Date xx/xx/xx". It should be noted that the accumulation start date is listed on each container, as it is contained in the unique drum number. For instance, drum number 020615-ABCDE-001 would indicate that this was the first drum received on a manifest from company ABCDE on June 15, 2002. Thus, the accumulation start date can be determined by looking at the first 6 digits of the unique drum number located on each drum. We have covered this item with our facility inspectors in the training listed above. Even though the accumulation start date was discernable, we relabeled the drum following the standard operating procedure. As noted in your Notice, this item was corrected during your inspection.

Citation:

KAR 28-31-4(j)(2). Improper start accumulation date on 2 55-gallon satellite drums in the Processing area.

Response:

During the inspection, two accumulation drums were noted with "Accumulation Start Date" labels of 6/1/02. As noted in your Notice, this item was corrected during your inspection. In addition, we covered this issue in the training listed above.

Citation:

Permit Condition II.A. Failure to maintain the roofs in Buildings B, J, I and D.

Response:

During the inspection, considerable rain fell in the Wichita area. The inspectors noted small puddles of water in Buildings B. J and I and a large accumulation of water was noted in Building D. Safety-Kleen's policy is to remove and rainwater collected in storage areas on a daily basis. In order to minimize future impacts of rainfall events, Safety-Kleen has notified a roofing contractor to attempt to repair the small leaks in the roofs of Buildings B, J and I. The extent of the roof repair needed for Building D is extensive and Safety-Kleen is currently evaluating the path forward for this area. Safety-Kleen has removed all waste managed in the area of the leak and will continue to remove collected rainwater from the area within 24 hours of each rainfall event.

Citation:

KAR 28-31-4(k) / Permit Condition III.G. 138 violations on the daily and weekly inspection logs (40 missing work orders, 71 no corrective action noted, 22 with no time, 5 didn't use full name).

Ms. Debbie Travis July 10, 2002 Page 3 of 4

Response:

During an extensive review of approximately 14 months of the facility's daily and weekly inspection records, the above violations were noted. The facility's inspection process utilizes a paperwork intensive combination of inspection forms and work orders. When an inspector notes a deficiency during an inspection, he is to complete a two-part work order, file one part with the Facility Manager and assign the other part to the employee who will correct the finding. Once the finding is corrected, the employee is to return his part of the work order to the Facility Manager. The agency's inspection noted 40 instances in which issues were identified on the daily inspections and work orders were issued, but copies of the work order were not filed with the Facility Manager, Additionally the agency noted 71 instances in which issues were noted (e.g., "warehouse floor needs to be swept", "loose bung in drum", etc.) but no corrective action was identified. Safety-Kleen believes that in these instances, the corrective action can be inferred but we agree with the finding that corrective action was not explicitly stated on the inspection form. Finally, the inspectors noted 27 instances in which either the time of the inspection was not noted or the full name of the inspector was not noted on the inspection forms.

Safety-Kleen has conducted retraining with all of our facility inspectors, covering the agency's findings and reviewing the work order process. Additionally, the Facility Manager will review each day's inspection for completeness and consistency.

Citation:

KAR 28-31-4(k) / Permit Condition III.G. Failure to provide 61 daily inspection logs for May and June 2001.

Response:

During the inspection, Safety-Kleen could not produce 2 months of inspections from May and June of 2001. The office in which these inspections were kept was recently cleaned and reorganized and the inspection records from those two months were misplaced. As a correction and as noted above, all daily and weekly inspection records are now submitted to the Facility Manager for review. Once that review is complete the inspection records will be placed in a central filing area.

Citation:

KAR 28-31-4(g) / 40 CFR 262, Subpart E / Permit Condition I.G. Failure to file a notice with the Secretary of KDHE for exporting hazardous waste to a foreign source 5 different times (3/14/01, 8/2/01, 11/8/01, 1/19/02 and 2/12/02).

Response:

Safety-Kleen has forwarded copies of the exportation reports, for the dates referenced in the NOV, to KDHE. In order to reduce the likelihood of future occurrences of this nature, the obligation to file export notices with KDHE, as required in K.A.R 2831-4(q), has been reviewed with the personnel responsible for making such notifications. Safety-Kleen has reviewed these incidences and maintains that the facility is in compliance with 40 CFR 262, Subpart E, since the facility did file the requisite notifications with EPA. Similarly, SK believes that it was not in violation of permit condition I.G. This condition requires that all reports, notices..."required by this permit".....be reported to KDHE. The permit does not require the facility to file export notifications.

Ms. Debbie Travis July 10, 2002 Page 4 of 4

Safety-Kleen regrets that these oversights occurred and would like to restate our commitment to resolving any and all environmental compliance matters identified by the Department, and it is our full intention to operate in total compliance with all Rules and Regulations of the State of Kansas and the USEPA. We trust that this submittal will fulfill the facility's outstanding obligations and conclude this matter.

Should you have questions or need any additional information regarding this matter, please feel free to contact our Regional Compliance Manager, Tom Emond, at (952) 898-0470, or myself at (316) 269-7400.

Sincerely,

Russell J. Dunn

Facility Manager

cc:

Tom Emond, SK Wichita Todd Blake, SK Reidsville Bill Hallam, SK Nashville Craig Lackey, SK Columbia

EHS file